

Selection & Specification Data

Generic Type Self-curing, water-based inorganic zinc primer.

Description

Carboweld 11 WB is a water-based inorganic zinc rich primer that protects steel galvanically, eliminating subfilm corrosion. It meets VOC regulations while providing the proven performance of silicate zinc rich technology. It may be used as a weldable pre-construction primer or as a primer under many different types

of topcoats.

Features

Excellent corrosion protection

High zinc loading per square foot

Zero VOC

Good resistance to saltingFast curing, quick handling

Excellent application characteristics (less likely

to pump packing or tip plug)

Color

Gray (0700) standard. Green (0300) and Red

(0500) available on special order.

Finish

Matte

Topcoats

May be topcoated with epoxies, acrylics, silicones, or others as recommended. (Mist coats over the CW 11 WB may be required to prevent

topcoat bubbling.)

Dry Film Thickness 0.75 - 1.25 mils (20 - 30 microns) per coat with

50 lbs. zinc for weldability applications

Don't exceed 6 mils (150 microns) in a single

coat.

Solids Content By Weight 73% ± 1%

Zinc content

77 ± 1%

By Weight
Theoretical

Carboweld 11 WB - 814 mil ft²

Allow for loss in mixing and application.

Coverage Rate (Per mixed gallon by ASTM D2697)

VOC Values As supplied or applied: 0 lbs./gal (0 g/l)

Dry Temp. Resistance Continuous: 750°F (399°C) Non-Continuous: 800°F (427°C)

Limitations Do not recoat/topcoat with itself.

Substrates & Surface Preparation

General

Remove any oil or grease from the surface to be coated with clean rags soaked in Carboline Thinner #2 or Surface Cleaner #3 (refer to Surface Cleaner #3 instructions) in accordance with SSPC-SP1.

Steel

Abrasive blast to a minimum commercial finish in accordance with SSPC-SP6 with a minimum 1 mil (25 microns) blast profile. An angular profile

will provide maximum adhesion.

Application Equipment

Listed below are general equipment guidelines for the application of this product. Job site conditions may require modifications to these guidelines to achieve the desired results.

General Guidelines:

Spray Application (General) Remove any oil or grease from the surface to be coated with clean rags soaked in Carboline Thinner #2 or Surface Cleaner #3 (refer to Surface Cleaner #3 instructions) in accordance

with SSPC-SP1.

Conventional Spray

Conventional spray is the preferred method of application for Carboweld 11 WB. Pressure pot equipped with dual regulators, 3/8" I.D. minimum material hose, with a maximum length of 50', 0.070" I.D. fluid tip and appropriate air cap.

Airless Spray

Airless spray is acceptable if some spray tails can be tolerated. Carboweld 11 WB may be

sprayed airless or conventional.

Pump Ratio: 30:1 (minimum)

GPM Output: 3.0 (minimum)

Material Hose: 3/8" I.D. (minimum)

Tip Size: 0.017-0.019"

Output PSI: 1750-2400

Filter Size: 60 mesh

Teflon packings are recommended and available from the pump manufacturer.

Prior to use, flush all equipment with Thinner #21 followed by clean potable water. Keep material under mild agitation during application. If spraying stops for more than 10 minutes, recirculate the material remaining in the spray line. Do not leave mixed primer in the hoses

during stoppages.

Brush & Roller (General)

Brush for touch-up only. Avoid excessive rebrushing. Use of a roller is not recommended.

Mixing & Thinning

Mixing Power mix base, then combine as follows:

Tip: Sifting zinc through a window screen will aid in the mixing process by breaking up or catching dry zinc

lumps.

 4.34 Gal Kit
 0.86 Gal Kit

 Part A:
 3.5 gallons
 0.70 Gal

 Zinc Filler:
 50 lbs.
 10 lbs

Note: Part A liquid base component is labeled

Carbozinc 11 WB/Carboweld 11 WB Base.

Thinning Not normally required. May be thinned up to 5% with

clean potable water.

Pot Life 8 hours at 75°F (24°C) and less at higher. Pot life ends

when the coating becomes too thick to use.

Cleanup & Safety

Cleanup Use clean, potable water. In case of spillage,

absorb and dispose of in accordance with local

applicable regulations.

Safety Read and follow all caution statements on this

product data sheet and on the MSDS for this product. Employ normal workmanlike safety precautions. Hypersensitive persons should wear protective clothing, gloves and use protective

cream on face, hands and all exposed areas.

Ventilation When used as a tank lining or in enclosed areas, thorough air circulation must be used during and

thorough air circulation must be used during and after application until the coating is cured. The ventilation system should be capable of preventing the solvent vapor concentration from reaching the lower explosion limit for the solvents used. User should test and monitor exposure levels to insure all personnel are below guidelines. If not sure or if not able to monitor

levels, use MSHA/NIOSH approved respirator.

All electrical equipment and installations should be made and grounded in accordance with the National Electric Code. In areas where explosion hazards exist, workmen should be required to

use non-ferrous tools and wear conductive and non-sparking shoes.

Application Conditions

Caution

Condition	Material	Surface	Ambient	Humidity
Normal	60-85°F (16°-30°C)	50-95°F (10°C- 35°C)	50-95°F (10°C- 35°C)	40-85%
Minimum	50°F (10°C)	40°F (4°C)	40°F (4°C)	30%
Maximum	95°F (35°C)	110°F (43°C)	110°F (43°C)	90%

This product simply requires the substrate temperature to be above the dew point. Condensation due to substrate temperatures below the dew point can cause flash rusting on prepared steel and interfere with proper adhesion to the substrate. Special application techniques may be required above or below normal application conditions.

Curing Schedule

Surface Temp. & 50% Relative Humidity	Dry to Handle	Dry to Topcoat
75°F (24°C)	30 minutes	18 hours

These times are based on a 3 mil (75 micron) dry film thickness. Higher film thickness, insufficient ventilation or cooler temperatures will require longer cure times and could result in solvent entrapment and premature failure. Excessive humidity or condensation on the surface during curing can interfere with the cure. Any loose salt that appears on the zinc surface as a result of prolonged weathering exposure must be removed prior to the application of additional coatings. Do not recoat/topcoat with itself.

Packaging, Handling & Storage

Shipping Weight

 (Approximate)
 4.34 Gal Kit
 0.86 Gal Kit

 Part A:
 42 lbs.
 9 lbs

 Zinc Filler:
 50 lbs.
 10 lbs

Flash Point None

(Setaflash)

Storage 40° -100°F (4-43°C)
Temperature 0-90% Relative Humidity

& Humidity Store indoors. Do not allow to freeze.

Shelf Life:

Carboweld 11 Base 18 months at 75°F (24°C)
Zinc Filler 24 months at 75°F (24°C)

*Shelf Life: (actual stated shelf life) when kept at recommended storage conditions and in original unopened containers.

Special Instructions Concerning Cure, Shipping and Storage

Carboweld 11 WB is an alkali silicate zinc rich primer. Like all water-based inorganic zinc primers trace amounts of alkalinity may remain within its film after cure. This alkaline residue can be detrimental to coating integrity when water is allowed to puddle on its surface. Use only steel storage, shipping and structural design configurations that prevent the puddling or trapping of water. Trace amounts of alkaline residue may concentrate in a drying puddle and result in high pH values that dissolve the coating film. Thorough rinsing reduces the likelihood or scope of the problem.



350 Hanley Industrial Court, St. Louis, MO 63144-1599 314/644-1000 314/644-4617 (fax) www.carboline.com

